



MITSUBISHI MOTORS AUSTRALIA LIMITED

ABN 53 007 870 395

Head Office

1284 South Road Clovelly Park, S.A. 5042

PO Box 8, Melrose Park South Australia 5039

Ph: +61 1300 13 12 11 Fax: +61 1300 55 33 19

Mitsubishi Motors Australia Limited (MMAL)

Recall Initiation Schedule

Version: 2.0

Issued: 3rd September 2018

Recall initiation date	9 th April 2018
Make and model	Make: Mitsubishi, Model: CS0A/W, CT9A Lancer
Model year	Affected vehicles were manufactured from 11 th June 2003 to 30 th December 2008
Geographic application	Not applicable
VIN list	VIN List provided when MMAL initiated this recall by submitting a request for a PRA to ACCC. https://www.mitsubishi-motors.com.au/uploads/pdf/recalls/20180403_VIN_List.pdf
Other factors	<p>This recall is initiated to rectify Mitsubishi Lancer vehicles which have already had their Takata airbag inflators replaced with Takata airbag inflators of the same type under PRA Number 2015/14936, Campaign Number 010093 which was published on 1st October 2015.</p> <p>This recall will rectify affected vehicles with a replacement airbag inflator manufactured by Daicel Corporation.</p>